Name of Work: GENERAL-Urgent Re Construction of Damaged Culvert at km 2/700 at Arikandampakku - Nenmini Church Road in Manjeri LAC



SECTIONAL DETAILS OF RCC CULVERT



SECTIONAL DETAILS OF RCC RETAINING WALL & CC DRAINAGE

All Dimensions are in Centimeters | Scale = 1:50 | Print Sheet - A4